^{32}P

Nuclide Safety Data Sheet Phosphorous-32

 ^{32}P

www.nchps.org

I. PHYSICAL DATA

Radiation: Beta (100% abundance)

Energy: Maximum: 1,710 keV; Average: 695 keV

Half-Life $[T_{1/2}]$: Physical $T_{1/2}$: 14.29 days

Biological $T_{1/2}$: Bone ~ 1155 days; Whole Body ~ 257 days¹

Effective T_{1/2}: 14.29 days

Specific Activity: 286,500 Ci/g [10,600 TBg/g] max.

Beta Range: Air: 610 cm [240 inches; 20 feet]

Water/Tissue: 0.76 cm [0.33 inches]
Plastic: 0.61 mm [3/8 inches]

II. RADIOLOGICAL DATA

Radiotoxicity²: Inhaled: 2.6E-8 Sv/Bq [95 mrem/uCi] Lung; 4.2E-9 Sv/Bq [16 mrem/uCi] CEDE

Ingested: 8.1E-9 Sv/Bg [30 mrem/uCi] Marrow; 2.4E-9 Sv/Bg [8.8 mrem/uCi] CEDE

Critical Organ: Bone [soluble ³²P]; Lung [Inhalation]; GI Tract [Ingestion - insoluble compounds]

Exposure Routes: Ingestion, inhalation, puncture, wound, skin contamination absorption

Radiological Hazard: External Exposure [unshielded dose rate at 1 mCi ³²P vial mouth³: approx. 26

rem/hr], Internal Exposure & Contamination

III. SHIELDING

Shield ³²P with 3/8 inch Plexiglas and monitor for Bremstrahlung; If Bremstrahlung X-rays detected outside Plexiglas, apply 1/8 to 1/4 inch lead [Pb] shielding outside Plexiglas
The accessible dose rate should be background but must be < 2 mR/hr

IV. DOSIMETRY MONITORING

VI. SPECIAL PRECAUTIONS

- Avoid skin contamination [absorption], ingestion, inhalation, & injection [all routes of intake].
- Store ³²P (including waste) behind Plexiglas shielding [3/8 inch thick]; survey (with GM meter) to check adequacy of shielding (accessible dose rate < 2 mR/hr; should be background); apply lead [Pb] shielding outside Plexiglas if needed.
- Use 3/8 inch Plexiglas shielding to minimize exposure while handling ³²P.
- Use tools [e.g. Beta Blocks] to handle ³²P sources and contaminated objects; avoid direct hand contact.
- Always have a portable survey meter present and turned on when handling ³²P.
- ³²P is not volatile, even when heated, and can be ignored as an airborne contaminant⁴ unless aerosolized.
- White vinegar can be an effective decontamination solvent for this nuclide in most forms.

² Federal Guidance Report No. 11 [Oak Ridge, TN; Oak Ridge National Laboratory, 1988], p. 122, 156

¹ NCRP Report No. 65, p.88

³ Dupont/NEN, <u>Phosphorous-32 Handling Precautions</u> [Boston, MA; NEN Products, 1985]

⁴ Bevelacqua, J. Contemporary Health Physics [New York; John Wiley & Sons, 1995], p. 282

VII. GENERAL PRECAUTIONS

- 1. Maintain your occupational exposure to radiation As Low As Reasonably Achievable [ALARA].
- 2. Ensure all persons handling radioactive material are trained, registered, & listed on an approved protocol.
- 3. Review the nuclide characteristics on (reverse side) prior to working with that nuclide. Review the protocol(s) authorizing the procedure to be performed and follow any additional precautions in the protocol. Contact the responsible Principal Investigator to view the protocol information.
- 4. Plan experiments to minimize external exposure by reducing exposure time, using shielding and increasing your distance from the radiation source. Reduce internal and external radiation dose by monitoring the worker and the work area after each use of radioactive material, then promptly cleaning up any contamination discovered. Use the smallest amount of radioisotope possible so as to minimize radiation dose and radioactive waste.
- 5. Keep an accurate inventory of radioactive material, including records of all receipts, transfers & disposal. Perform and record regular lab surveys.
- 6. Provide for safe disposal of radioactive waste by following institutional Waste Handling & Disposal Procedures. Avoid generating mixed waste (combinations of radioactive, biological, and chemical waste). Note lab staff are not permitted to pour measurable quantities of radioactive material down the drain.